



**TWINGO
MODUS
CLIO
CLIO 2
CLIO III
KANGOO
MEGANE
SCENIC
MEGANE II
SCENIC II
LAGUNA
LAGUNA II
ESPACE
ESPACE IV
VEL SATIS
LOGAN**

Type

XXXX

Cancels and replaces Technical Note no. 4664A dated DECEMBER 2006.

Modifications: Changes to wiring kit.

17B VEHICLE DOES NOT START, INTERMITTENT ENGINE HESITATION AND STALLING

Other sub-section concerned:

13B

17A

- Engine: **D4D, D4F, D7D, D7F, E7F, E7J, F3R, F3P, F4P, F4R, F5R, F7P, F8Q, F9Q, G9T, K4J, K4M, K7J, K7M, K9K, M9R, XXX**
- Gearbox:

Basic manual:
Technical Note: **6015A**

"The repair procedures given by the manufacturer in this document are based on the technical specifications current when it was prepared.

The procedures may be modified as a result of changes introduced by the manufacturer in the production of the various component units and accessories from which the vehicles are constructed."

All rights reserved by **RENAULT S.A.S.**

Copying or translating, in part or in full, of this document or use of the service part reference numbering system is forbidden without the prior written authority of **RENAULT S.A.S.**

INJECTION

Position and engine speed sensor

17B

TECHNICAL DATA

Customer complaint

Intermittently:

- Engine hesitation and stalling.
- Vehicle does not start.

Possible cause

- Poor contact between the connector and the Top Dead Centre (**TDC**) sensor.

Fault finding

- Confirm the customer complaint.
- Use the diagnostic tool to check for one or more of the following fault codes:

Petrol engine:

- DF005
- DF017
- DF025
- DF080
- DF154
- DF189
- DF238

Diesel engine:

- DF005
- DF023
- DF088
- DF120
- DF213

Operation to be carried out

- Replacement of TDC sensor and connector.

Description of the operation

REMOVAL

- Remove:
 - The TDC sensor,
 - the connector by cutting the TDC wiring as close as possible to the connector.

REFITTING

IMPORTANT

It is **ESSENTIAL** to respect the foolproof device on the connector with reference to the new TDC sensor. Changes are possible to the colour and shape of the TDC sensors and connectors.

- Connect the TDC sensor wiring kit to the TDC wiring (see **Technical Note 6015A**).
- Refit the new TDC sensor.
- Reconnect the TDC wiring.

INJECTION

Position and engine speed sensor

17B

CLAIM COMPLETION AND CODING

When to take action

- Upon receipt of a customer complaint.

Parts required

According to the Replacement Parts Catalogue or Dialogys.

1	TDC sensor
---	------------

NOTE

Ordering the TDC sensor automatically generates an order for the associated TDC sensor wiring kit

Depending on the colour and shape of the **NEW** TDC sensor (spare part):

With ROUND BLACK TDC sensor connector

Quantity and description of parts	Part number
1 TDC sensor wiring kit	82 00 673 203

NOTE

The **ROUND BLACK TDC sensor connector (8200673203)** can be replaced with the special **SQUARE kit (8200652822)**.

With ROUND BLUE TDC sensor connector

Quantity and description of parts	Part number
1 TDC sensor wiring kit	82 00 673 202

With SQUARE BLACK TDC sensor connector

Quantity and description of parts	Part number
1 TDC sensor wiring kit	82 00 300 322

With SQUARE TDC sensor connector specific to M9R engine

Quantity and description of parts	Part number
1 TDC sensor wiring kit	82 00 652 822

IMPORTANT

It is essential to respect the polarity of the lines when switching from a **ROUND** connector to a **SQUARE** connector.

Line A=A or line A=1

Line B=B or line B=2

Time required

Code	Description	Time
0311	Complete computer check	Depending on operation time
0500	Replace the connector	0.5
Depending on operation time	Remove-refit TDC sensor	depending on operation time
	TOTAL	depending on operation time

Destination of removed parts

- In accordance with warranty directives.

Codification procedures

- Cause part number: **TDC sensor**
(In accordance with the "Spare Parts" Catalogue or Dialogys)

- **Without PGCS**

- NITG code: **M518**

- **With or without PGCS**

- Supplier code: **050**
- Customer complaint code: **7A, 7B, 7C, 8B**