



Base is intact but missing the outer brackets.



Brackets required to secure the base to the chassis