



	Type	S/Section
CLIO II	<div>XB0X</div>	<div>30</div>

30

CHANGE IN THE TIGHTENING TORQUE FOR THE SHOCK ABSORBER TURRET

Other sub-section concerned :

31


- Engine:

XXX
- Gearbox :

XXX

Basic manual : M.R. 337

Change in the torque for tightening the shock absorber turret mounting bolts. The torque indicated in the documents was 18 daN.m. The actual torque required is 10.5 daN.m.



* Compulsory direction for fitting