



# CLIO 2

Type

Fabrication cut-offs

CB0 M

K000003 to K006957

Y000001 to Y002504

*fitted with F4R 730 engine*

## 18A ENGINE OIL CAP ACCESS FLAP LOST OR VIBRATING

Other sub-section concerned: 09A

- Engine: F4R 730
- Gearbox: XXX

Basic manual: XXX

### CUSTOMER COMPLAINT

– Noise in the engine compartment.

### POSSIBLE CAUSE

– Closure of the oil filler cap access flap located on the engine cover.

### CLAIM COMPLETION AND CODING

#### Destination of removed parts:

– As per Warranty Policy and Procedures Manual.

- Without PGCS

NITG code: A354

- With PGCS

Catalogue function: 033

Cause reference: 82 00 186 031

- With or without PGCS

Supplier code: H47

Customer complaint code: 5S

Operation code: 1999

Title: Replacement of the access flap

Total time allowed: 0.3 h

"The repair methods given by the manufacturer in this document are based on the technical specifications current when it was prepared.

The methods may be modified as a result of changes introduced by the manufacturer in the production of the various component units and accessories from which his vehicles are constructed."

All copyrights reserved by Renault.

Copying or translating, in part or in full, of this document or use of the service part reference numbering system is forbidden without the prior written authority of Renault.

### AFTER-SALES SOLUTION

#### Operation to be carried out:

- Replace the engine oil filler cap access flap located on the engine cover.

#### Vehicles concerned:

- See vehicle types and fabrication cut-off details on title page.

#### When to take action:

- Upon receipt of a customer complaint.

#### Parts required:

- 1 filler cap access flap      **Part no.: 82 00 186 031**


#### Tooling required:

- Conventional.

#### Description of the operation:

- Replace the engine oil filler access flap (A) (**Fig. 1**).

**Note:** This operation avoids replacing the whole cover.



**Fig. 1**

- A - Engine oil filler access flap
- B - Engine cover