

Vehicle Information

Brand: PEUGEOT	VIN: VF3CUHNZTHY094863	Plate Number:
Model: 2008	Mileage: 0.0	Color:
Year:	Capacity:	Status: Unset status
Engine:	Reference:	Date: 04.12.2022 14:41:29

Automatic scanning results

System Name	Status/Count
01-Built-in systems interface-BSI2010	Fault 24
02-Engine management ECU-VD46	Fault 1
03-Automatic or piloted manual gearbox-BVA_AM6_AT6_UDS	Pass No Fault
04-Anti-lock Braking System (ABS) or Electronic Stability Program (ESP)-ESPMK100	Pass No Fault
05-Airbags and pretensioners ECU-RBG_UDS	Fault 2
06-Touch screen-EMF_DGT_LVDS_BD	Fault 1
07-Controls on the steering wheel / Integral controls steering wheel	There may be sub-system.
08-Power steering-DAE	Pass No Fault
09-Air conditioning	There may be sub-system.
10-Control panel dot matrix display-MATT_C_2010	Pass No Fault
11-Parking assistance-AAS_UDS	Fault 12
12-Vehicle Distance Assistance-LIDAR	Pass No Fault
13-Battery charge status control unit-BECB_GEN2	Pass No Fault
14-Controls under the steering wheel-COM2008P	Fault 1

15-Multifunction control panel-FMUX	Pass No Fault
16-Instrument panel-COMBINE_UDS	Pass No Fault
17-Voltage maintaining device-DMTR_DTC3B	Fault 3
18-Rain and brightness sensor-PLUIE_LUMINOSITE_UDS	Pass No Fault
19-Telematic unit (RTx) or audio-navigation	There may be sub-system.
20-Traction control mode selector-ASR	Pass No Fault

Built-in systems interface-BSI2010

ID	Status	Description
C1651-86	Permanent	Confirmation of the taking into account of the indirect tyre under-inflation detection function reference drives database reinitialisation request-Confirmation not emitted by the ESP or not taken into account by the built-in systems interface
B1140-15	Permanent	Front left foglamp control fault-Open circuit or short circuit to positive
B1153-62	Permanent	Windscreen wiper park information fault-Coherence
B1296-87	Permanent	Fault of lack of coherence of the information used by the emergency collision braking (in town) function
B1418-00	Permanent	Fault in the status of the seat belt fastening information for determining the presence of the driver
B162B-11	Intermittent	Fault: CAN+ relay control and status not coherent-Relay controlled But Inactive
B162C-12	Permanent	Fault: accessories positive relay control and status not coherent-Relay not activated But Active
B173A-00	Permanent	Fault in the status of the driver's door for the determination of driver presence
B173D-86	Permanent	Fault in identifying the mechanical/electronic key or the hands-free remote control present in the reader-Identifier Invalid
B1805-62	Permanent	Starter fault-Coherence

B1808-87	Permanent	Fault in the unlocking of the immobiliser by the engine management ECU-Request missing
B1825-84	Permanent	Oil level information fault-Level too low
U1802-86	Permanent	Vehicle speed data fault-Signal not valid
U1F00-00	Intermittent	Fault event not stored in the faults log
U1F15-08	Permanent	Fault: ECU not communicating on the Entertainment Information CAN
U1F1B-08	Permanent	LIN fault 2
U1F22-87	Permanent	Fault: no communication with the parking assistance ECU
U1F25-87	Permanent	Fault: absence of communication with the instrument panel
U1F38-87	Permanent	Fault: absence of communication with the instrument panel matrix display
U1F39-87	Permanent	Fault: no communication with the rain/brightness sensor
U1F3E-87	Permanent	Fault: no communication with telematic ECU
U1F40-87	Permanent	Fault: absence of communication with the battery charge status control unit
U1F42-87	Permanent	Fault: no communication with air conditioning ECU
U1F43-87	Permanent	Fault: absence of communication with the airbags and pre-tensioners unit

Engine management ECU-VD46

ID	Status	Description
P15A1-21	Intermittent	Lubrication system-Oil pressure too low in mechanical mode

Airbags and pretensioners ECU-RBG_UDS

ID	Status	Description
----	--------	-------------

[B1400-16](#) Intermittent CAN + supply voltage fault

[B1400-64](#) Intermittent CAN + supply voltage fault

Touch screen-EMF_DGT_LVDS_BD

ID	Status	Description
B1574-1C	Intermittent	Multifunction touch screen ECU-Voltage outside range

Parking assistance-AAS_UDS

ID	Status	Description
B1218-87	Intermittent	Absence of a datastream from the ESP ECU-Message missing
B1219-87	Intermittent	Fault in the electric power steering status information for the semi-automatic parking system-Message missing
B1221-92	Intermittent	Inner front left parking assistance sensor fault-Operation or performance incorrect
B1222-92	Intermittent	Outer front left parking assistance sensor fault-Operation or performance incorrect
B1225-92	Intermittent	Inner front right parking assistance sensor fault-Operation or performance incorrect
B1226-92	Intermittent	Outer front right parking assistance sensor fault-Operation or performance incorrect
B1228-92	Intermittent	Outer rear right parking assistance sensor fault-Operation or performance incorrect
B1251-92	Intermittent	Front right lateral parking assistance sensor fault-Operation or performance incorrect
U1804-87	Intermittent	Fault: steering wheel angle information-Message missing
U1805-87	Intermittent	Wheel pulse counters information fault-Message missing
U1F00-00	Permanent	Event not recorded fault-Not characterised

U1F2E-87	Intermittent	Absence of communication with the engine management ECU- Message missing
--------------------------	--------------	---

Controls under the steering wheel-COM2008P

ID	Status	Description
B100C-16	Intermittent	ECU supply fault-Voltage too low

Voltage maintaining device-DMTR_DTC3B

ID	Status	Description
B1004	Intermittent	Network voltage maintaining device internal fault-
P1B71	Intermittent	Network voltage maintaining device triggering line fault-Short circuit to earth or open circuit
U1F2E	Intermittent	Absence of communication with the engine management ECU-

Contact Information

Name: SCA BALLARAT

Address: Shop 1 333 Gillies Street Ballarat

Phone: 03 5339 9455

Email:

Website: www.supercheapauto.com.au