

Company:

Address:

Telephone:

# Report

2024-04-13 14:16

## Vehicle Information

Vehicle Name : 2008

Year: 2019

VIN: VF3CUHMZ0KY153263

Mileage : 0km

SN: D7-020518

Diagnosis Route : PEUGEOT V11.65

## Fault Codes

28 systems detected: 6 systems related to fault codes, 19 fault codes

NO.	System Name	Status
1	<b>built-in systems interface</b>	▲ 14
	U1F43	Fault: absence of communication with the airbags and pre-tensioners unit
	U1F2E	Fault: no communication with engine ECU
	B173D	Fault in identifying the mechanical/electronic key or the hands-free remote control present in the reader
	B1808	Fault in the unlocking of the immobiliser by the engine management ECU
	U1802	vehicle speed data fault
	B1178	Front left direction indicator and left-hand side repeater control fault
	B162C	Fault: accessories positive relay control and status not coherent
	B1627	battery charge status unit : voltage sensor fault
	B1816	Fault: loss of the hybrid drive train status information or of the starting authorisation information from the engine management ECU
	B1418	Fault in the status of the seat belt fastening information for determining the presence of the driver
	U1809	oil temperature information fault
	B132F	Air conditioning high pressure information fault
	U1F0E	Transmission and reception fault on the Intersystems CAN/ High speed CAN 1
	U1F00	Fault event not stored in the faults log
2	<b>battery charge status control unit</b>	▲ 1
	B1627	battery charge status unit : voltage sensor fault
3	<b>airbags and pretensioners ECU</b>	▲ 1
	U1802	vehicle speed data fault
4	<b>rain and sunlight sensor</b>	▲ 1
	U1802	vehicle speed data fault.
5	<b>touch screen</b>	▲ 1
	B1574	Multifunction touch screen ECU
6	<b>elematic unit (RTx) or audio-navigation</b>	▲ 1
	B100C	RCC connected audio system electrical supply
7	engine management ECU	✓
8	diesel fuel additive pump	✓
9	Voltage maintaining device	✓
10	automatic or piloted manual gearbox	✓
11	power steering	✓
12	Anti-lock Braking System (ABS) or Electronic Stability Program (ESP)	✓
13	railer relay unit	✓
14	instrument panel	✓
15	Control panel dot matrix display	✓

16	controls under the steering wheel	✓
17	Controls on the steering wheel/Integral controls steering wheel	✓
18	raction control mode selector	✓
19	Multifunction control panel	✓
20	Vehicle Distance Assistance	✓
21	parking assistance	✓
22	radio	✓
23	Service module / Independent telematic unit	✓
24	external CD player	✓
25	audio amplifier	✓
26	anti-theft alarm	✓
27	Intrusion alarm siren	✓
28	air conditioning	✓

Remark:

\*This report is only responsible for the results of this detection: